

March 13, 1998

ASQ-208A-B Page 1 of 1

Date No

## **Bulletin**

**Type** 

**Ö** Parts Manual Update

Policy Letter

Service Information

**Attention** Service Managers

Ö Service and Parts Managers

Models LWD27AW, LWA80A\*, LWC80A\*, LWA90A\* and LWC90A\*

Issue Correction to Parts Manual RP3100005 Revision 0.

Action Make these corrections in your paper manual as listed. No further notices or revisions will be

provided. Microfiche and CD-ROM information will be updated.

Model/Mfg No.	Page No.	Image No.	Ref No.	Corrections
LWD27AW PLWD27AW	4	_	_	Changed designator to call for two speed motor, was single speed motor
LWA80A* PLWA80A*	13	_	5	35118 Action Switch was 38367
LWC80A* PLCA80A*	13	_	5	35118 Action Switch was 38367
LWA90A* PLWA90A*	15	_	19	Added Ref # 19 34837 Bulb-Light (not shown)
LWC90A* PLCA90A*	15	_	19	Added Ref # 19 34837 Bulb-Light (not shown)
LWA90A* PLWA90A*	15	_	20	Added Ref # 20 34841 Starter (not shown)
LWC90A* PLCA90A*	15	_	20	Added Ref # 20 34841 Starter (not shown)