TECHNICAL SERVICE POINTER FOR IMMEDIATE ATTENTION OF YOUR SERVICE DEPARTMENT

M LAUNDRY PRODUCTS

REFRIGERATION PRODUCTS

This Service Pointer Applies To The Following Brands:

W10410553 April 2011

[™] Whirlpool[®] □ KitchenAid[®]

M Amana[®]

□Roper®

□ Jenn-Air[®] □ Admiral[®]

Maytag[®] ∟ □Magic Chef[®]

Amana, Estate, Crosley, Maytag and Whirlpool Dryers

Drum may not ride on front panel bearing block

Models:

IV85001	NGD5100TQ1	NED5100TQ1	CED126SXQ0
CGD126SXQ0	CEDX631VQ1	7MMGP0035WQ0	WED4750XQ0
WGD4750XQ0	WED5590VQ1	WGD5590VQ1	

Serial Range: M044 - M103

Customer Concern:

Drum may not ride on front panel bearing block, see figure 1. This may also damage the right hand support roller.



Correction:

Order replacement drum assembly and right hand support roller. Order by model number.

Figure 1

Note: Inspect the rear bulkhead and the right hand support roller shaft for damage. Order by model number and replace if needed.