


Hoover HDE2000GW 07 - WIRING INFORMATION



CONNECT DRYER TO 230 V.A.C. 50 HZ. 1 PHASE INDIVIDUAL BRANCH CIRCUIT PROTECTED BY MAXIMUM 30 A. FUSES. ALWAYS GIVE THE SERIAL & MODEL NUMBERS WHEN WRITING ABOUT THIS DRYER OR ORDERING PARTS

Hoover [Residential Hoover HDE2000GW Dryer Parts](#) Parts Diagram 07 - WIRING INFORMATION
 Click on the part number to view part

Item	Original Part Number	Replaced By	Status	Part Description
NI	15001220		Not Available	WIRING INFORMATION

