

Dexter WCAD20KCS-12 (T300) Labels And Diagrams

the laundry company[®]

No Parts Drawing



the laundry company[®]

[Dexter Commercial Dexter WCAD20KCS-12 \(T300\) Washer Parts](#) Parts Diagram Labels And Diagrams

[Click on the part number to view part](#)

Item	Original Part Number	Replaced By	Status	Part Description
*	9506-117-001		Not Available	Wiring Diagram, Coin (120 V)
"	9506-117-001		Not Available	Wiring Diagram, Coin (120 V)
"	9506-131-001		Not Available	Wiring Diagram, Coin, Electronic Acceptor (120 V)
"	9506-103-001		Not Available	Wiring Diagram Easy Card (120 V)
"	9506-390-001		Not Available	Wiring Diagram, CN, No Acceptor (120 V)
"	9506-119-001		Not Available	Wiring Diagram, Coin
"	9506-119-001		Not Available	Wiring Diagram, Coin
"	9506-133-001		Not Available	Wiring Diagram, Coin, Electronic Acceptor
"	9506-105-001		Not Available	Wiring Diagram (Easy Card)

"	9506-392-001	Not Available	Wiring Diagram, CN, No Acceptor
"	8507-273-001	Not Available	Instructions Spin Direction
"	9506-116-001	Not Available	Wiring Schematic, Coin (120 V)
"	9506-116-001	Not Available	Wiring Schematic, Coin (120 V)
"	9506-130-001	Not Available	Wiring Schematic, Coin, Electronic Acceptor (120 V)
"	9506-102-001	Not Available	Wiring Schematic, Easy Card (120 V)
"	9506-389-001	Not Available	Wiring Schematic, CN, (120V) No Acceptor
"	9506-118-001	Not Available	Wiring Schematic, Coin
"	9506-118-001	Not Available	Wiring Schematic, Coin
"	9506-132-001	Not Available	Wiring Schematic, Coin, Electronic Acceptor
"	9506-104-001	Not Available	Wiring Schematic, Easy Card
"	9506-391-001	Not Available	Wiring Schematic, CN, No Acceptor
"	8507-330-001	Not Available	Instruction Transient Voltage Suppressor
"	8502-614-004		Label-Warning,High voltage
"	8502-619-004		Label Fusing & Installation
"	8511-001-002	Not Available	Label Quality
"	8514-167-001	Not Available	Booklet Owners